



<First Notification>

March 8, 2018

To: Our Valued Customers

Re: MAERSK HONAM (V.806W) – Fire on board on 6th March 2018

It is regrettable to inform you that the MAERSK HONAM reported a serious fire in one of the cargo holds on 6th March whilst approximately 900 nautical miles southeast of Salalah, Oman while on a laden voyage from Singapore to Suez.

The cause of damage is not known yet but will be thoroughly investigated, and it has not yet been reported by the vessel owner which containers were affected by fire.

We have received a situation update from Maersk Line today (below), and will make sure that you are notified once we have additional information from the vessel owner.

We do apologize for your inconvenience. Should you have any questions or comments, please feel free to contact your local Hyundai Representative in your area.

Situation update about AE11 – MAERSK HONAM

We regret to inform you that AE11 MAERSK HONAM 441W reported a serious fire in one of the cargo holds on 06 March. Enrouting from Singapore towards Suez, the vessel is currently positioned around 900 nautical miles southeast of Salalah, Oman.

23 members have been successfully evacuated and search rescue are ongoing for four crew members currently reported missing.

The cause of the fire is currently unknown. Maersk Line will investigate the matter thoroughly in cooperation with all relevant authorities.

The vessel is carrying 7860 containers. All impacted customers will be contacted directly.

We are working on the contingency for the cargo on board MAERSK HONAM and will communicate updates as we receive them.

For any questions, please feel free to contact your local customer service or sales representatives. You will find contact details of our local office on www.maerskline.com.

Yours sincerely,
Maersk Line Greater China Cluster

Sincerely,
Hyundai Merchant Marine Co., Ltd